



U2		HT46R46	
1	PA3/PFD	48	PA4/TMR
2	PA2	17	PA5/TNT
3	PA1	16	PA6
4	PA0	15	PA7
5	PB3/AN3	14	OSC1
6	PB2/AN2	13	OSC2
7	PB1/AN1	12	+5V
8	PB0/AN0	11	VDD
9	VSS	10	PWM
			RES
			PDO/PWM